

# Certificate of Inspection

Company Name:

Suit Style:

Suit No:

Inspection Date:

Inspected & Tested by: **James Wellington**  
Senior Drysuit Technician

Findings: Leaks found in right back thigh and left hamstring.

Visual inspection shows no signs of excess wear, fabric still in good serviceable condition. Zip passed visual inspection.

Repairs carried out: Patching to right thigh and left hamstring.

Next Inspection due: July 2014

Next Inspection Recommendations: General inspection and service. Nothing of concern showing on suit. Next inspection in 12 months.

Recommended Care Instructions: Use silicone zip lubricant as supplied with suit when purchased every few months. Wash thoroughly in fresh water to remove salt crystal build up which can damage the membrane of the fabric. Keep out of direct sunlight when not in use.

Checked & Signed Off by: **Chris Hammond** Director



Date Released: 18 July 2013

# HAMMOND

Unit 2 Dene Yard - Green Street Green Road - Dartford - Kent - DA2 7PB - UK  
00 44 (0)1474 704123 [www.hammond-drysuits.co.uk](http://www.hammond-drysuits.co.uk)